




FIG.1




**FIG.2**




# FIG.3




**FIG.4**




**FIG.5**



**FIG.6**




**FIG.7**




4 : OPTICAL SIGNAL  
— TRANSMISSION SUBSTRATE




**FIG.8**





# FIG.9



-  LIGHT EMITTING ELEMENT E<sub>XY</sub>  
(TRANSMISSION FROM LAYER X TO LAYER Y)
-  LIGHT RECEIVING ELEMENT D<sub>XY</sub>  
(TRANSMISSION FROM LAYER X TO LAYER Y)
-  TRANSMITTABLE WINDOW T

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**